



USTRAC

## Facility C&amp;E Summary

Owner Name and Address: Frank Coluccio Construction Inc. 9600 MLK Way S. Seattle WA 98118

Facility ID	Location Name	Location Street Address	Location City State	Zip	County	Tribe	C&E Status	LUST Status
WA2676	Frank Coluccio Construction Inc.	9600 MLK Way S.	Seattle, WA	98118	King		Closed	NA

## Facility Actions:

Date	Inspector	Action	Penalty	SOC UST Status	SOC	Last Due Date	Last Closed Date	Citation
03/01/07	Adam Baron	Field Citation	\$150.00	Operating	Not Either	04/01/07	05/04/07	350(3)(a) Failure to provide adequate line leak detector system for underground piping
		FNNC	\$0.00			04/01/07	05/04/07	355(2) Failure to maintain results of sampling, testing or monitoring for release detection for at least 1 year or failure to retain results of tightness testing until next test is conducted



# USTRAC

## Facility Summary

Owner Name and Address: Frank Coluccio Construction Inc. 9600 MLK Way S. Seattle WA 98118

Facility ID	Location Name	Location Street Address	Location City State	Zip	County	Tribe	SOC	C&E Status	LUST
WA2676	Frank Coluccio Construction Inc.	9600 MLK Way S.	Seattle, WA 98118	98118	King		Not Either	Closed	NA

### Financial Responsibility

Type	Issuer	Policy Number	Effective Date Start	Effective Date End
Insurance	Colony Insurance		1/7/2006	1/7/2007

### Contacts

Contact Name: Address: City State Zip: Phone: Fax: Email:

### Tank Summary

M\* = Manifold; C\*=Compartment

Tank ID	Status	M* C* Installed	Closed	Product	Capacity	Tank Material / Sec. Mat.	Piping Material / Sec. Mat. / Type	Over / Spill / CP
1	Currently in Use	No No 1/1/1973		Diesel	30000	Cathodically Protected Steel	Fiberglass Reinforced Plastic Double-Walled	Pressurized Yes Yes Yes
2	Currently in Use	No No 1/1/1973		Diesel	30000	Cathodically Protected Steel	Fiberglass Reinforced Plastic Double-Walled	Pressurized Yes Yes Yes
3	Currently in Use	No No 1/1/1973		Diesel	10000	Cathodically Protected Steel	Fiberglass Reinforced Plastic Double-Walled	Pressurized Yes Yes Yes
4	Currently in Use	No No 1/1/1973		Gasoline	10000	Cathodically Protected Steel	Fiberglass Reinforced Plastic Double-Walled	Pressurized Yes Yes Yes
5	Currently in Use	No No 1/1/1973		Diesel	10000	Cathodically Protected Steel	Fiberglass Reinforced Plastic Double-Walled	Safe Suction Yes Yes Yes
6	Currently in Use	No No 1/1/1973		Gasoline	10000	Cathodically Protected Steel	Fiberglass Reinforced Plastic Double-Walled	Safe Suction Yes Yes Yes



# USTRAC

## Facility Summary

### Facility Actions

Inspection Date	Inspector	Action	SOC	C & E Status	SOC UST Status	Last Due Date	Closed Date	Number of Violations	Outstanding Violations
03/01/07	Adam Baron	Field Citation	Not Either Requirement	Closed	Operating	4/1/2007	5/4/2007	1	0
03/01/07	Adam Baron	FNNC	Not Either Requirement	Closed	Operating	4/1/2007	5/4/2007	1	0

### Lust Events

Event Date	LUST Status	Manager	Last Milestone	Last Closed Date
------------	-------------	---------	----------------	------------------

### Facility General Comments



USTRAC

## Facility Tank Summary

Owner Name and Address: Frank Coluccio Construction Inc. 9600 MLK Way S. Seattle WA 98118

Facility ID	Location Name	Location Street Address	Location City State	Zip	County	Tribe	SOC	C&E Status	LUST
WA2676	Frank Coluccio Construction Inc.	9600 MLK Way S.	Seattle, WA	98118	King		Not Either	Closed	NA

Tank	Status	M*	C*	Installed	Closed	Product	Capacity	Tank Material / Sec. Mat.	Piping Material / Sec. Mat.	Type	Over / Spill / CP			
1	Currently in Use	No	No	1/1/1973		Diesel	30000	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Double-Walled	Pressurized	Yes	Yes	Yes
2	Currently in Use	No	No	1/1/1973		Diesel	30000	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Double-Walled	Pressurized	Yes	Yes	Yes
3	Currently in Use	No	No	1/1/1973		Diesel	10000	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Double-Walled	Pressurized	Yes	Yes	Yes
4	Currently in Use	No	No	1/1/1973		Gasoline	10000	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Double-Walled	Pressurized	Yes	Yes	Yes
5	Currently in Use	No	No	1/1/1973		Diesel	10000	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Double-Walled	Safe Suction	Yes	Yes	Yes
6	Currently in Use	No	No	1/1/1973		Gasoline	10000	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Double-Walled	Safe Suction	Yes	Yes	Yes